



Digital Audio Corporation
A DRI Company
5121 Holly Ridge Drive
Raleigh, NC 27612
Phone 919.782.6767
Fax 919.782.6766
www.dacaudio.com

DAC Technical Support Bulletin
Release Date: January 10, 2003
TSBSBR05

Subject: “Run-Time Error ‘1001’ ” error when running international versions of Windows.

Version of the SSABR software prior to 2.0.2 will exhibit a “Run-Time Error ‘1001’” after clicking the “Configure” button in the CDU application on Windows operating systems using non-12-hour time formats. The work-around for pre-2.0.2 versions of the SSABR software is to set the time display setting to a 12-hour format (HH:MM:SS AM/PM) via the “Regional Options” within the Windows Control Panel.

Version 2.0.2 (available for download at www.dacaudio.com/support.html) has corrected this problem and will work with other locale time formats.

Andy Jarrell
SSABR Project Engineer