



Digital Audio Corporation
A DRI Company
5121 Holly Ridge Drive
Raleigh, NC 27612
Phone 919.782.6767
Fax 919.782.6766
www.dacaudio.com

DAC Technical Support Bulletin
Release Date: October 7, 2002
TSBSBR03

Subject: Installation problem with Version 2.0.0 on Windows XP

At the end of the installation SSABR Version 2.0.0 software an option to view the "Readme" file is given. This file ("Readme.rtf") details the installation procedure of the USB drivers on Windows XP. This file refers to a folder on the installation CD named "Drivers". This folder was mistakenly not included on the installation CD.

This issue has been corrected in version 2.0.1 of the software. For customers with version 2.0.0, the drivers file can be downloaded from the support section of the Digital Audio Corporation website:

<http://www.dacaudio.com/support.html>

Go to the "Software Upgrades" section of the website.

To install these drivers, download the self-extracting executable ("USBdrivers.exe") to a temporary folder on the same computer that the SSABR software is installed. Running this executable will extract the driver files the default folder of "C:\SSABR USB Drivers" or into a folder of your choice. The drivers necessary for your operating system are located in the folder for that specific operating system. For example, the Windows XP files are located in the folder "C:\SSABR USB Drivers\WindowsXP".

Upon connecting the SSABR unit via USB you will be prompted for the drivers. Direct the computer to look in the folder mentioned above. During this driver installation, you may be prompted for "WinRT for USB" files. Point the driver installation process to this same folder.

We apologize for any inconvenience these issues have caused. Please do not hesitate to contact us at 1-877-532-2283 if you have any other questions or concerns.

Andy Jarrell
SSABR Project Engineer