



Digital Audio Corporation
A DRI Company
5121 Holly Ridge Drive
Raleigh, NC 27612
Phone 919.782.6767
Fax 919.782.6766
www.dacaudio.com

DAC Technical Support Bulletin
Release Date: October 7, 2002
TSBSBR04

Subject: "Invalid Image File" error when inserting image file CD.

Version 2.0.0 offered a new feature of automatically putting the Image File Player (IFP) application on the same CD as the image file. A special file named "Autorun.inf" is placed on this CD along with the IFP and the IFP online help file. This special file directs Windows to automatically open the image file in the IFP when the CD is inserted.

A problem exists in Version 2.0.0 whereby the IFP will load, but a message is displayed that reads, "Unable to open file. Invalid Image File". This problem occurs because of an incorrectly created "Autorun.inf" file. The image file may still be loaded by selecting the "Open" option from the File Menu in the IFP and selecting the image file located on the CD.

This issue has been corrected in version 2.0.1 of the software. Please contact Digital Audio Corporation to receive an updated software CD. We apologize for any inconvenience these issues have caused. Please do not hesitate to contact us at 1-877-532-2283 if you have any other questions or concerns.

Andy Jarrell
SSABR Project Engineer