

## ADDENDUM

### HTX-420 2-Meter/70 cm Dual Band FM Amateur Transceiver

Cat. No. 19-1108

Please note the following information regarding the operation of your transceiver.

1. **CO-ERR** appears on the subdisplay when the transceiver does not detect compass data. To correct the problem, calibrate the electronic compass. See "Using the Electronic Compass" on Page 43 of the Owner's Manual.
2. If **ERR** appears on the main display, take the transceiver to your local RadioShack store for assistance.

© 2001 RadioShack Corporation  
All Rights Reserved.

RadioShack is a registered trademark used by RadioShack Corporation.

---